

VEHICLE INSPECTION REPORT

DK67VYT

Man TGM 18.250

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date	22/12/2017	Colour	BLUE	Cab Type	DAY CAB
Year	2017	VIN	WMAN08ZZ8JY368681	Gearbox	AUTOMATIC
Mileage	136,943 Km Warranted	Body Style	Dropside & Crane	Axle Combi	4x2
Fuel Type	Diesel	MOT Due	31/03/2026	Rear Suspension	Steel

HMF 1420-KR REMOTE CRANE (YEAR 2017), SHEETING SYSTEM, SERVICE SCHEDULE LIST AVAILABLE

Tyres


NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features

- Bluetooth connection
- Cruise control
- Park assist camera
- Digital radio
- Front electric windows
- Central locking
- Cloth seat trim


Photos







Condition Check



Damage Photos



1: Door osf
Scratched
Over 25mm Thru Paint



2: Panel Front
Missing
Replace



3: Bumper Front Moulding
Scuffed (Unpainted)
Over 100mm



4: Bonnet
Chipped
Multiple Chips



5: Bumper Front Moulding
Scuffed (Unpainted)
Over 100mm



6: Bumper Front Moulding
Broken
Replace



7: Door Pad osf
Broken
Replace



8: Dash Warning Lights
Displayed
No Action

Interior

Carpet Condition	OK	Upholstery Condition	Poor
Seat Condition	OK	Odour	-
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	Fault	DPF light illuminated	OK
ABS light illuminated	OK		