

# VEHICLE INSPECTION REPORT

**SJ19Nzc**

## Volvo FMX 420

### Inspection

Serious Damage? No

### Vehicle

VAT Plus VAT

V5 Present

### Details

Reg. date 14/03/2019

Year 2019

Mileage 350,956 Km Not Warranted

Fuel Type Diesel

Colour WHITE

VIN YV2XTW0G0KB888400

Body Style Tipper

MOT Due 31/10/2025

Cab Type DAY CAB

Gearbox AUTOMATIC

Axle Combi 8x4

Rear Suspension Steel

\*WARNING LIGHT ON DASH\* ABBA PREDATOR BODY, HYVA TIPPING GEAR, SURROUND CAMERA SYSTEM, SHEETING SYSTEM

### Tyres

NSF NSI1 NSI2 NSI3 NSI4

OSF OSI1 OSI2 OSI3 OSI4


Spare NSO1 NSO2 NSO3 NSO4

OSO1 OSO2 OSO3 OSO4

## Features

- Park assist camera
- Air conditioning

## Photos












## Condition Check



## Damage Photos



1: Bumper Front  
Scratched  
25 to 100mm Thru Paint



2: Fog Lamp Surround os  
Scratched (Painted)  
UpTo 25mm Thru Paint





3: Other  
N/A  
N/A



4: Screen Front  
Chipped  
Over 10mm



5: Bumper Front  
Scratched  
25 to 100mm Thru Paint



6: Other  
N/A  
N/A



7: Door Moulding nsf  
Scuffed (Unpainted)  
UpTo 100mm



8: Door Mirror Glass ns  
Broken  
Replace



9: Other  
N/A  
N/A



10: Other  
N/A  
N/A



11: Door osf  
Scratched  
UpTo 25mm Thru Paint



12: Door osf  
Scratched  
UpTo 25mm Thru Paint



13: Other  
N/A  
N/A



14: Door osf  
Chipped  
Edge Chip





15: Seat Base Cover osf  
Burn  
Over 3mm

Interior

| Carpet Condition         |                    | Upholstery Condition                           |              |
|--------------------------|--------------------|------------------------------------------------|--------------|
| Seat Condition           | Average<br>Average | Odour                                          | Average<br>- |
| Engine Runs              | OK                 | Gearbox 1st and Reverse Test                   | OK           |
| Brakes                   | OK                 | Clutch Slip Test from Static                   | OK           |
| Parking Brake            | OK                 | Gearbox Static Gear Selection (engine running) | OK           |
|                          |                    | No Excessive Smoking                           | OK           |
| EML light illuminated    | Fault              | Oil warning light illuminated                  | OK           |
| Airbag light illuminated | OK                 | DPF light illuminated                          | OK           |
| ABS light illuminated    | OK                 | Service indicator light illuminated            | OK           |