

VEHICLE INSPECTION REPORT

NA65UJB

Scania P 250

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 To Follow

Details

Reg. date	07/01/2016	VIN	YS2P4X20005407808	Cab Type	DAY CAB
Year	2016	Body Style	Fridge Box	Gearbox	AUTOMATIC
Mileage	796,521 Km Warranted	Service history	Yes	Axle Combi	4x2
Fuel Type	Diesel	Service documents	Printout	Rear Suspension	Air
Colour	WHITE	MOT Due	31/08/2026		

THERMOKING UNIT

Tyres


NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features


- Bluetooth connection
- Radio/CD
- Central locking
- Cruise control
- Air conditioning
- Cloth seat trim
- Auxiliary input socket
- Front electric windows
- Digital radio
- Drivers airbag

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Panel Front
Cracked
Replace



3: Door Mirror Assy nsf
Scuffed (Unpainted)
Over 100mm



4: Door nsf
Dented
With Paint Damage



5: Door nsf
Scratched
Over 25mm Thru Paint



6: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



7: Qtr Panel osr
Scratched
Over 25mm Thru Paint



8: Door Mirror Assy osf
Broken
Replace



9: Door osf
Dented
With Paint Damage



10: Seat Base Cover nsf
Soiled
Heavy



11: Seat Base Cover osf
Soiled
Heavy

Interior

Carpet Condition	OK	Upholstery Condition	OK
Seat Condition	Poor	Odour	-
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		