

# VEHICLE INSPECTION REPORT

**YR69GDY**

## Ford Transit Connect 240 1.5 EcoBlue 100ps

### Inspection

Conditions	Outdoors - Good light
Serious Damage?	No

### Vehicle

VAT	Plus VAT
V5	Buyer To Apply

### Details

Reg. date	18/12/2019
Year	2019
Mileage	47,099 Miles Warranted
Fuel Type	Diesel
Colour	WHITE
VIN	WF0SXXWPGSKU02841

Body Style	Panel Van L2
MOT Due	17/12/2025
CAP Clean	£6,800.00
CAP Average	£5,925.00
CAP Below	£4,775.00
Gearbox	MANUAL

Gears	6
Doors	2
Axle Combi	4x2
Rear Suspension	Steel
Rear Doors	Barn

AD - BLUE

### Tyres

NSF

NSR

OSF

OSR


Spare

## Features

- Bluetooth connection
- Radio/CD


## Photos







## Condition Check



## Damage Photos



1: Carpets Front  
Soiled  
Heavy



2: Bumper Front  
Chipped  
1 To 5



3: Door osf  
Dented  
2 Or Less UpTo 10mm



4: Bumper Rear Moulding  
Scuffed (Unpainted)  
UpTo 100mm

Interior

Carpet Condition		Average	Upholstery Condition		Average
Seat Condition		Average	Odour		No
Engine Runs	OK		Gearbox 1st and Reverse Test	OK	
Brakes	OK		Clutch Slip Test from Static	OK	
Turbo Boosting	OK		Gearbox Static Gear Selection (engine running)	OK	
Parking Brake	OK		No Excessive Smoking	OK	
EML light illuminated	OK		Oil warning light illuminated	OK	
Airbag light illuminated	OK		DPF light illuminated	OK	
ABS light illuminated	OK		Service indicator light illuminated	OK	
Windows	OK		Radio	OK	
			Steering	OK	