

VEHICLE INSPECTION REPORT

BL18ZDJ

Ford Transit Connect 1.5 TDCi 100ps

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT
V5 Buyer To Apply

Details

Reg. date	10/08/2018	Body Style	Panel Van L1	Gears	5
Year	2018	MOT Due	09/08/2025	Doors	2
Mileage	137,865 Miles Warranted	CAP Clean	£2,925.00	Axle Combi	4x2
Fuel Type	Diesel	CAP Average	£2,525.00	Rear Suspension	Steel
Colour	WHITE	CAP Below	£1,950.00		
VIN	WF0RXXWPGRJJ00733	Gearbox	MANUAL		

SINGLE SIDE DOOR

Tyres

NSF

NSR

OSF


OSR


Spare

Features


- Radio/Cassette

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
1 To 5



2: Wing of
Chipped
1 To 5



3: Door osf
Dented
Between 10mm + 30mm



4: Qtr Panel osr
Dented
With Paint Damage



5: Tailgate
Dented
With Paint Damage



6: Qtr Panel nsr
Dented
2 Or Less UpTo 10mm

Interior

Carpet Condition		Average	Upholstery Condition		Average
Seat Condition		Average	Odour		No
Engine Runs	OK		Gearbox 1st and Reverse Test	OK	
Brakes	OK		Clutch Slip Test from Static	OK	
Turbo Boosting	OK		Gearbox Static Gear Selection (engine running)	OK	
Parking Brake	OK		No Excessive Smoking	OK	
EML light illuminated	OK		Oil warning light illuminated	OK	
Airbag light illuminated	OK		DPF light illuminated	OK	
ABS light illuminated	OK		Service indicator light illuminated	OK	

Windows	OK	Radio	OK
		Steering	OK