

VEHICLE INSPECTION REPORT

LN68SSU

ISUZU F 135.240

Inspection

Vehicle

VAT	Plus VAT
V5	Present

Details

Reg. date	04/09/2018	VIN	JALFSR90NH7000209	Axle Combi	4x2
Year	2018	Body Style	Fridge Box	Rear Suspension	Steel
Mileage	199,721 Km Warranted	MOT Due	31/01/2026	Rear Doors	Barn
Fuel Type	Diesel	Cab Type	DAY CAB		
Colour	WHITE	Gearbox	AUTOMATIC		

750MT CARRIER UNIT, STANDBY PLUG, SURROUND CAMERA SYSTEM

Tyres

NSF
NSR
OSF
OSR
Spare

Features

- Park assist camera

Photos





