

## VEHICLE INSPECTION REPORT

**CV22XRA**

### Vauxhall Movano 3500 2.2 TURBO 140PS

#### Inspection

Serious Damage? No

#### Vehicle

VAT Plus VAT

V5 Buyer To Apply

#### Details

Reg. date 29/04/2022

Year 2022

Mileage 108,740 Miles Not Warranted

Fuel Type Diesel

Colour WHITE

VIN VXEYDBPFC12U96977

Body Style Luton L3

MOT Due 28/04/2026

Gearbox MANUAL

Gears 6

\*WARNING LIGHTS ON DASH\* AD-BLUE, E/MIRRORS

#### Tyres

NSF

NSR

OSF

OSR

Spare

## Features


- Navigation system
- Air conditioning
- Front electric windows

## Photos





## Condition Check



## Damage Photos



1: Bonnet  
Chipped  
Multiple Chips



2: Screen Front  
Chipped  
Over 10mm



3: Bumper Front Moulding  
Scuffed (Unpainted)  
UpTo 100mm



4: Door Mirror Assy nsf  
Scuffed (Unpainted)  
UpTo 100mm



5: Qtr Panel nsr  
Scratched  
Over 25mm Thru Paint



6: Door Mirror Assy osf  
Broken  
Replace

## Interior

| Carpet Condition         |                    | Upholstery Condition                           |               |
|--------------------------|--------------------|------------------------------------------------|---------------|
| Seat Condition           | Average<br>Average | Odour                                          | Average<br>No |
| Engine Runs              | OK                 | Gearbox 1st and Reverse Test                   | OK            |
| Brakes                   | OK                 | Clutch Slip Test from Static                   | OK            |
| Parking Brake            | OK                 | Gearbox Static Gear Selection (engine running) | OK            |
|                          |                    | No Excessive Smoking                           | OK            |
| EML light illuminated    | Fault              | Oil warning light illuminated                  | OK            |
| Airbag light illuminated | OK                 | DPF light illuminated                          | OK            |
| ABS light illuminated    | OK                 | Service indicator light illuminated            | OK            |