

VEHICLE INSPECTION REPORT

LN68SSO

ISUZU N 75.190

Inspection

Vehicle

VAT	Plus VAT
V5	Present

Details

Reg. date	04/09/2018	VIN	JAANPR75KH7102185	Axle Combi	4x2
Year	2018	Body Style	Fridge Box	Rear Suspension	Steel
Mileage	352,002 Km Warranted	MOT Due	30/09/2026	Rear Doors	Barn
Fuel Type	Diesel	Cab Type	DAY CAB		
Colour	WHITE	Gearbox	AUTOMATIC		

WARNING LIGHT ON DASH XARIOS 600 CARRIER UNIT, STANDBY PLUG, SURROUND CAMERA SYSTEM

Tyres

NSF
NSR
OSF
OSR
Spare

Features

- Park assist camera

Photos





