

VEHICLE INSPECTION REPORT

FD15VWB

DAF LF 280

Inspection

Vehicle

VAT	Plus VAT
V5	Present

Details

Reg. date	17/07/2015	Body Style	Fridge Box	Axle Combi	4x2
Year	2015	Service history	Yes	Rear Suspension	Steel
Mileage	289,030 Km Not Warranted	Service documents	Printout	Rear Doors	Roller
Fuel Type	Diesel	MOT Due	30/09/2026	Tail Lift	Column
Colour	CREAM/BROWN	Cab Type	DAY CAB		
VIN	XLRAEL3700L444823	Gearbox	AUTOMATIC		

Tyres

NSF

NSR

OSF

OSR

Spare

Features

- Park assist camera
- Digital radio

Photos



