

VEHICLE INSPECTION REPORT

WS190DB

MERCEDES-BENZ SPRINTER 314 CDI

Inspection

Vehicle

| | |
|-----|----------|
| VAT | Plus VAT |
| V5 | Present |

Details

| | | | | | |
|-----------|----------------------------|------------|-------------------|-------------|-----------|
| Reg. date | 29/08/2019 | VIN | WDB9101332N018126 | CAP Average | £5,300.00 |
| Year | 2019 | Body Style | Dropside LWB | CAP Below | £4,225.00 |
| Mileage | 162,387 Miles Warranted | Keys | 2 | Gearbox | MANUAL |
| Fuel Type | Diesel | MOT Due | 10/09/2025 | Axle Combi | 4x2 |
| Colour | WHITE | CAP Clean | £6,050.00 | | |

TOW BAR, E/WINDOWS, REAR VIEW CAMERA
WARNING LIGHT ON DASH

Tyres

| |
|-------|
| NSF |
| NSR |
| OSF |
| OSR |
| Spare |

Features

- Park assist camera
- Front electric windows

Photos



