

VEHICLE INSPECTION REPORT

BK72DXV

FORD TRANSIT 350 2.0 ECOBLUE 130PS

Vehicle

No	VAT	Plus VAT		
	V5	Present		
25/10/2022	VIN	WF0EXXTTRENU57266	CAP Below	£10,400.00
2022	Body Style	Panel Van L3	Gearbox	MANUAL
30,671 Miles Warranted	MOT Due	02/11/2026	Gears	6
	CAP Clean	£13,050.00		
Diesel	CAP Average	£12.050.00		
WHITE				
	25/10/2022 2022 30,671 Miles Warranted Diesel	25/10/2022 VIN 2022 Body Style 30,671 Miles MOT Due Warranted CAP Clean Diesel CAP Average	V5 Present 25/10/2022 VIN WF0EXXTTRENU57266 2022 Body Style Panel Van L3 30,671 Miles MOT Due 02/11/2026 Warranted CAP Clean £13,050.00 Diesel CAP Average £12,050.00	V5 Present 25/10/2022 VIN WF0EXXTTRENU57266 CAP Below 2022 Body Style Panel Van L3 Gearbox 30,671 Miles MOT Due 02/11/2026 Gears Warranted CAP Clean £13,050.00 Diesel CAP Average £12,050.00

AD-BLUE, SIDE LOAD DOOR

ı	yres	

Inspection

NSF

NSR

OSF

OSR

Spare

Features

- · Bluetooth connection
- · Digital radio
- Pässenger airbag
- · Front parking sensor
- Air conditioning
- Central locking
- · Rear parking sensor
- Front electric windows
- Cloth seat trim
- Auxiliary input socket
- Drivers airbag

Photos

















Condition Check



Damage Photos



1: Bonnet Scratched Over 25mm Thru Paint



2: Bonnet Scratched Over 25mm Thru Paint



3: Door nsf Scratched Over 25mm Not Thru Paint



4: Fuel Flap Missing Replace



5: Qtr Panel nsr Dented Over 30mm



6: Qtr Panel nsr Dented With Paint Damage



7: C Post ns Scratched Over 25mm Thru Paint



8: Door nsr Scratched Over 25mm Thru Paint



9: Door nsr Scratched Over 25mm Thru Paint



10: Qtr Panel osr Dented With Paint Damage



11: Qtr Panel Moulding os Scuffed (Unpainted) Over 100mm



12: Qtr Panel Moulding os Scuffed (Unpainted) Over 100mm



13: Door Mirror Assy osf Broken Replace



14: Seat Base Cover nsf Soiled Heavy

Interior

Carpet Condition Seat Condition	OK Poor	•	holstery Condition our	OK No	
Engine Runs	1 001		lo Excessive Smoking	110	OK
EML light illuminated		OK D	PF light illuminated		OK
ABS light illuminated		OK			