

VEHICLE INSPECTION REPORT

HD69AXZ

ISUZU FORWARD N75.150

Inspection

Vehicle

VAT	Plus VAT
V5	Present

Details

Reg. date	04/02/2020	VIN	JAANPR85KK7100150	Gearbox	AUTOMATIC
Year	2020	Body Style	Curtainside	Axle Combi	4x2
Mileage	345,406 Km Warranted	Service history	Yes	Rear Suspension	Steel
Fuel Type	Diesel	MOT Due	31/05/2026	Rear Doors	Roller
Colour	WHITE	Cab Type	DAY CAB		

WARNING LIGHT ON DASH SURROUND CAMERA SYSTEM

Tyres

NSF

NSR

OSF

OSR

Spare

Features

- Park assist camera

Photos



