

VEHICLE INSPECTION REPORT

AE20PZO

ISUZU N75.190

Inspection

Vehicle

VAT	Plus VAT
V5	Present

Details

Reg. date	30/04/2020	VIN	JAANPR75KK7103142	Gearbox	AUTOMATIC
Year	2020	Body Style	Curtainside	Axle Combi	4x2
Mileage	421,878 Km Warranted	Service history	Yes	Rear Suspension	Steel
Fuel Type	Diesel	MOT Due	30/04/2026	Tail Lift	Cantilever
Colour	WHITE	Cab Type	DAY CAB		

Tyres

NSF	
NSR	
OSF	
OSR	
Spare	

Features

- Air conditioning