

VEHICLE INSPECTION REPORT

Vehicle VAT CV68FLZ

ISUZU D-MAX 1.9

Inspection

| | | V5 | To Follow | | |
|-----------|---------------------------|-------------|-------------------|------------|--------|
| Details | | | | | |
| Reg. date | 07/09/2018 | VIN | MPATFS87JHT018859 | Gearbox | MANUAL |
| Year | 2018 | Body Style | Pickup Double Cab | Gears | 6 |
| Mileage | 14,643 Miles Warranted | CAP Clean | £10,300.00 | Axle Combi | 4x4 |
| | | CAP Average | £8,875.00 | | |
| Fuel Type | Diesel | CAP Below | £6,925.00 | | |
| Colour | SILVER | | , | | |

Plus VAT

NEEDS EASYSTART TO START, ENGINE NOISE, SMOKES WHEN HOT SUSPECTED INJECTOR FAULTS E/ MORRORS, TOW BAR

Tyres NSF

NSR

OSF

OSR

Spare

Features

Air conditioning

· Front electric windows

• Central locking

Photos





















