

VEHICLE INSPECTION REPORT

C457517

MONTRACON FRIDGE BOX

Inspection

Vehicle

VAT	Plus VAT
V5	N/A

Details

Reg. date	01/01/2017	VIN	SMRR2ACCCHN121601	Steering Combi	Rear Steer
Year	2017	Body Style	Trailer	Rear Suspension	Air
Mileage	13,367 Hours Not Showing	MOT Due	28/02/2026	Rear Doors	Roller
Fuel Type		Brakes	Drum	Tail Lift	Column
Colour	WHITE	Axle Combi	Tandem		

FRIDGE HOUSING DAMAGED BPW AXLES, CARRIER VECTOR 1950MT UNIT, PARTITION DOORS, 2 LANE BODY, RAISE & LOWER VALVE, FERRY LASHING RINGS, STANDBY PLUG

Tyres

NSF
NSR
OSF
OSR
Spare

Photos





