

VEHICLE INSPECTION REPORT

C356025

DON BUR BOX

Inspection

Vehicle

VAT	Plus VAT
V5	N/A

Details

Reg. date	01/01/2013	VIN	SEPBV38GKDL061890	Brakes	Disc
Year	2013	Body Style	Trailer	Axle Combi	Tri
Mileage	Not Showing	Service history	Yes	Steering Combi	Front Lift
Fuel Type		Service documents	Printout	Rear Suspension	Air
Colour	RED	MOT Due	31/03/2026	Rear Doors	Roller

CORROSION, CRACKED FRAME BPW AXLES, RAISE & LOWER VALVE, FERRY LASHING RINGS

Tyres

NSF
NSR
OSF
OSR
Spare