

VEHICLE INSPECTION REPORT

YG73UKZ

Maxus T90 130KW ELITE 88.5KWH EV

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 To Follow

Details

Reg. date 29/12/2023

Year 2023

Mileage 53,286 Miles
Warranted

Fuel Type Electric

Colour WHITE

VIN LSFAM1202NA153887

Body Style Pickup Double Cab

CAP Clean £9,125.00

CAP Average £8,625.00

CAP Below £7,575.00

Gearbox AUTOMATIC

Gears 6

E/ MIRRORS, HEATED WINDSCREEN, FIRST MOT DUE 28/12/2026

Tyres

NSF

NSR

OSF

OSR


Spare

Features

- Bluetooth connection
- Digital radio
- Drivers airbag
- Park assist camera
- Air conditioning
- Passenger airbag
- Rear parking sensor
- Front electric windows
- Central locking
- Auxiliary input socket
- Rear electric windows
- Leather seat trim


Photos







Condition Check



Damage Photos



1: Door Mirror Assy osf
Scratched (Painted)
Over 25mm Thru Paint



2: Door Pad osr
Scuffed
Over 25mm



3: Carpets Front
 Holed
 Over 3mm

Interior

Carpet Condition		Poor	Upholstery Condition		Poor
Seat Condition		OK	Odour		-
Engine Runs	OK		Gearbox 1st and Reverse Test	OK	
Brakes	OK		Clutch Slip Test from Static	OK	
Turbo Boosting	OK		Gearbox Static Gear Selection (engine running)	OK	
Parking Brake	OK		No Excessive Smoking	OK	
EML light illuminated	OK		Oil warning light illuminated	OK	
Airbag light illuminated	OK		DPF light illuminated	OK	
ABS light illuminated	OK		Service indicator light illuminated	OK	