

VEHICLE INSPECTION REPORT

YG73ULC

Maxus T90 130KW ELITE 88.5KWH EV

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 To Follow

Details

Reg. date 29/12/2023

Year 2023

Mileage 31,212 Miles
Warranted

Fuel Type Electric

Colour WHITE

VIN LSFAM1201NA153878

Body Style Pickup Double Cab

CAP Clean £10,250.00

CAP Average £9,675.00

CAP Below £8,500.00

Gearbox AUTOMATIC

Gears 6

Axle Combi 4x4

E/ MIRRORS, FIRST MOT DUE 28/12/2026

Tyres

NSF

NSR

OSF

OSR


Spare

Features

- Bluetooth connection
- Air conditioning
- Passenger airbag
- Park assist camera
- Front electric windows
- Central locking
- Rear parking sensor
- Rear electric windows
- Leather seat trim
- Digital radio
- Drivers airbag


Photos







Condition Check



Damage Photos



1: Bumper Front
Scratched
Over 100mm Thru Paint



2: Wheel nsf
Scratched
Over 50mm



3: Door Mirror Assy nsf
Scratched (Painted)
Over 25mm Thru Paint

4: C Post ns
Dented
With Paint Damage



5: Qtr Panel nsr
Dented
With Paint Damage

6: Qtr Panel nsr
Dented
With Paint Damage



7: Qtr Panel nsr
Dented
With Paint Damage

8: Bumper Front
Scratched
25 to 100mm Thru Paint



9: Door Pad osr
Scuffed
Over 25mm

10: Door Pad nsr
Scuffed
Over 25mm



11: Wiper nsf
Broken
Replace

Interior

Carpet Condition		Upholstery Condition	
Seat Condition		Odour	
Poor	Poor	Poor	Poor
OK	OK	No	No
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK