

VEHICLE INSPECTION REPORT

YG73ULA

Maxus T90 130KW ELITE 88.5KWH EV

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 To Follow

Details

Reg. date 29/12/2023

Year 2023

Mileage 18,078 Miles
Warranted

Fuel Type Electric

Colour WHITE

VIN LSFAM1201NA153881

Body Style Pickup Double Cab

CAP Clean £10,950.00

CAP Average £10,350.00

CAP Below £9,100.00

Gearbox AUTOMATIC

Gears 6

CRACK IN WINDSCREEN E/ MIRRORS, FIRST MOT DUE 28/12/2026

Tyres

NSF

NSR

OSF

OSR


Spare

Features

- Bluetooth connection
- Digital radio
- Passenger airbag
- Park assist camera
- Air conditioning
- Central locking
- Rear parking sensor
- Front electric windows
- Leather seat trim
- Auxiliary input socket
- Drivers airbag


Photos







Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips

2: Bumper Front
Scratched
25 to 100mm Thru Paint



3: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint

4: Bumper Rear Moulding
Broken
Replace



5: Tailgate
Dented
With Paint Damage

6: Qtr Panel osr
Dented
Over 30mm



7: Qtr Panel osr
Dented
Over 30mm

8: Screen Front
Cracked
Replace



9: Door Pad osr
Scuffed
Over 25mm

10: Door Pad nsr
Scuffed
Over 25mm



11: Carpets Front
Holed
Over 3mm

12: Dash Warning Lights
Displayed
No Action

Interior

Carpet Condition Poor
Seat Condition OK

Upholstery Condition Poor
Odour No

Airbag light illuminated Fault