

VEHICLE INSPECTION REPORT

YG73ULK

Maxus T90 130KW ELITE 88.5KWH EV

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 To Follow

Details

Reg. date 29/12/2023

Year 2023

Mileage 16,452 Miles
Warranted

Fuel Type Electric

Colour WHITE

VIN LSFAM1202NA153873

Body Style Pickup Double Cab

CAP Clean £11,050.00

CAP Average £10,450.00

CAP Below £9,200.00

Gearbox AUTOMATIC

Gears 6

WARNING LIGHT ON DASH HEATED WINDSCREEN, E/ MIRRORS, FIRST MOT DUE 28/12/2026

Tyres

NSF

NSR

OSF

OSR




Spare

Features

- Bluetooth connection
- Digital radio
- Passenger airbag
- Park assist camera
- Front electric windows
- Central locking
- Rear parking sensor
- Rear electric windows
- Leather seat trim
- Auxiliary input socket
- Drivers airbag


Photos







Condition Check



Damage Photos



1: Tailgate
Dented
With Paint Damage

2: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint



3: Bumper Front
Chipped
Over 5mm

4: Door Pad osr
Scuffed
Over 25mm



5: Dash Warning Lights
Displayed
No Action

Interior

Carpet Condition	OK
Seat Condition	OK

Upholstery Condition	Poor
Odour	No

Service indicator light illuminated	Fault
-------------------------------------	-------