

VEHICLE INSPECTION REPORT

PN74DXD

Daf LF 260

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date 01/11/2024

Year 2024

Mileage 16,881 Km Warranted

Fuel Type Diesel

Colour WHITE

VIN XLRAEL3700L528041

Body Style Box Van

Cab Type DAY CAB

Gearbox AUTOMATIC

Axle Combi 4x2

Rear Suspension Air

Rear Doors Roller

Tail Lift Column

FIRST MOT DUE 30/11/2025

Tyres

NSF NSI1

NSI2

NSI3

NSI4

OSF OSI1

OSI2

OSI3

OSI4

Spare NSO1

NSO2

NSO3

NSO4

OSO1

OSO2

OSO3



OSO4

Features

- Bluetooth connection
- Cruise control
- Park assist camera
- Digital radio
- Front electric windows
- Central locking
- Cloth seat trim


Photos







Condition Check



Damage Photos



1: Bumper Front
Scratched
25 to 100mm Thru Paint

2: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint

Interior

Carpet Condition	OK	Upholstery Condition	OK
Seat Condition	OK	Odour	-
Engine Runs	OK	No Excessive Smoking	OK

EML light illuminated

OK

DPF light illuminated

OK

ABS light illuminated

OK