

VEHICLE INSPECTION REPORT

SL62XBC

SCANIA R 560

Inspection

Vehicle

VAT	Plus VAT
V5	Buyer To Apply

Details

Reg. date	01/01/2013	Colour	WHITE	Gearbox	AUTOMATIC
Year	2013	VIN	YS2R6X20005309135	Axle Combi	6x2
Mileage	1,376,785 Km Not Warranted	Body Style	Tractor Unit	Steering Combi	Mid-Lift Steer
Fuel Type	Diesel	Cab Type	TOPLINE CAB	Rear Suspension	Air

WARNING LIGHT ON DASH TWIN FUEL TANKS, SLIDING 5TH WHEEL

Tyres

NSF
NSR
OSF
OSR
Spare

Features

- Leather seat trim

Photos



