

## VEHICLE INSPECTION REPORT

**ST68UEH**

### Ford Transit Connect 220 1.5 EcoBlue 75PS

**Non Runner**

#### Inspection

Serious Damage? No

#### Vehicle

VAT Plus VAT

V5 To Follow

#### Details

Reg. date 16/11/2018

Year 2018

Mileage 70,667 Miles  
Warranted

Fuel Type Diesel

Colour WHITE

VIN WF0RXXWPGRJB61534

Body Style Panel Van L1

MOT Due Expired

CAP Clean £4,800.00

CAP Average £4,150.00

CAP Below £3,225.00

Gearbox MANUAL

Gears 6

\*ENGINE PART STRIPPED\* SIDE LOAD DOOR.

#### Tyres

NSF

NSR

OSF


OSR


Spare

## Features


- Radio/CD
- Front electric windows
- Central locking
- Leather seat trim

## Photos





## Condition Check



## Damage Photos



1: Door osf  
Dented  
Over 30mm

2: Qtr Panel osr  
Dented  
Over 30mm



3: Tailgate  
 Chipped  
 1 To 5

Interior

| Carpet Condition         |  | Average | Upholstery Condition                           |  | Average |
|--------------------------|--|---------|------------------------------------------------|--|---------|
| Seat Condition           |  | Average | Odour                                          |  | No      |
| Engine Runs              |  | Fault   | Gearbox 1st and Reverse Test                   |  | OK      |
| Brakes                   |  | Fault   | Clutch Slip Test from Static                   |  | OK      |
| Turbo Boosting           |  | Fault   | Gearbox Static Gear Selection (engine running) |  | Fault   |
| Parking Brake            |  | Fault   | No Excessive Smoking                           |  | Fault   |
| EML light illuminated    |  | Fault   | Oil warning light illuminated                  |  | Fault   |
| Airbag light illuminated |  | Fault   | Service indicator light illuminated            |  | Fault   |
| ABS light illuminated    |  | Fault   |                                                |  |         |
| Windows                  |  | OK      | Radio                                          |  | OK      |