

VEHICLE INSPECTION REPORT

WU22YTW

Iveco S-Way 570

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Buyer To Apply

Details

Reg. date 22/07/2022

Year 2022

Mileage 359,387 Km Not Warranted

Fuel Type Diesel

Colour WHITE

VIN WJMS62NW40C474433

Body Style Tractor Unit

MOT Due 30/04/2026

Cab Type AT SLEEPER CAB

Gearbox AUTOMATIC

Axle Combi 6x2

Steering Combi Mid-Lift

Tyres

NSF NSI1

NSI2

NSI3

NSI4

OSF OSI1

OSI2

OSI3

OSI4

Spare NSO1

NSO2

NSO3

NSO4

OSO1

OSO2

OSO3

OSO4

Features


- Navigation system
- Air conditioning

Photos





Condition Check



Damage Photos



1: Qtr Panel Arch Extension ns
Broken
Replace



2: Other
N/A
N/A

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour -

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK