

VEHICLE INSPECTION REPORT

YR69DVO

Ford Transit Custom 280 2.0 EcoBlue 105ps LEADER

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 To Follow

Details

Reg. date 20/09/2019

Year 2019

Mileage 109,077 Miles
Warranted

Fuel Type Diesel

Colour WHITE

VIN WF0YXXTTGYKY80321

Body Style Panel Van L1

MOT Due 19/07/2026

CAP Clean £5,500.00

CAP Average £4,850.00

CAP Below £3,850.00

Gearbox MANUAL

Gears 6

ONLY STARTS WITH BOOSTER PACK SIDE LOAD DOOR, AD-BLUE, POWER INVERTER, 240V SOCKETS, 12V OUTLETS

Tyres

NSF

NSR

OSF

OSR

Spare


Features

- Bluetooth connection
- Front electric windows
- Cloth seat trim
- Park assist camera
- Drivers airbag
- Rear parking sensor
- Passenger airbag
- Digital radio
- Central locking


Photos







Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips

2: Roof
Chipped
Multiple Chips



3: Bumper Front
Insecure
Action Required

4: Qtr Panel nsr
Chipped
Multiple Chips




5: Qtr Panel nsr
Dented
With Paint Damage

6: Qtr Panel nsr
Dented
With Paint Damage



7: Door nsr
Scratched
Over 25mm Thru Paint

8: Door osr
Scratched
Over 25mm Thru Paint





9: Qtr Panel osr
Dented
With Paint Damage

10: Door osf
Scratched
Over 25mm Thru Paint



11: Fascia Panel
Missing
Replace

12: Seat Base Cover osf
Torn
Over 3mm



13: Bumper Front
Dented
Over 30mm

Interior

Carpet Condition	Average	Upholstery Condition	Poor
Seat Condition	Poor	Odour	No
Engine Runs	Fault	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		