

VEHICLE INSPECTION REPORT

KP67HXU

VOLVO FE 280 6X2

Inspection

Vehicle

VAT	Plus VAT
V5	Present

Details

Reg. date	30/11/2017	Colour	MULTI-COLOURED	Gearbox	AUTOMATIC
Year	2017	VIN	YV2V0Y1C0HZ115479	Axle Combi	6x2
Mileage	4,398,512 Km Warranted	Body Style	Curtainside	Rear Suspension	Air
Fuel Type	Diesel	MOT Due	31/01/2026	Rear Doors	Barn

REAR-LIFT

Tyres

NSF

NSR

OSF

OSR

Spare

Features

- Park assist camera
- Air conditioning

Photos





