

VEHICLE INSPECTION REPORT

WN12CJX

Mercedes-Benz Sprinter 513 CDI

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date 30/03/2012

VIN WDB9066532S671380

Gearbox MANUAL

Year 2012

Body Style Access Platform

Axle Combi 4x2

Mileage 234,393 Km Warranted

Service history Yes

Rear Suspension Steel

Fuel Type Diesel

Service documents Electronic / Online

Colour WHITE

MOT Due Expired

BUCKET DAMAGED - STRUCTURAL CRACK, DO NOT OPERATE LIFT & BUCKET VERSALIFT ET 36 NF
EUROTEL 36L (YEAR 2012), 145642 MILES

Tyres

NSF NSI1

NSI2

NSI3

NSI4

OSF OSI1

OSI2

OSI3

OSI4

Spare NSO1

NSO2

NSO3

NSO4

OSO1

OSO2

OSO3





OSO4



Features

- Cruise control
- Front electric windows
- Park assist camera
- Drivers airbag
- Digital radio
- Central locking
- Radio/CD
- Partial leather seat trim


Photos







Condition Check



Damage Photos



1: Bumper Front
Scratched
Over 100mm Thru Paint



2: Bumper Front
Scratched
Over 25mm Not Thru Paint



3: Bumper Front
Dented
With Paint Damage

4: Panel Front
Chipped
Multiple Chips



5: Panel Rear
Chipped
Multiple Chips

6: Panel Front
Dented
Over 30mm



7: Sill Panel Trim ns
Scuffed (Unpainted)
Over 100mm

8: Panel Rear
Scratched
Rusted



9: Qtr Panel osr
Chipped
Multiple Chips

10: Sill os
Chipped
Multiple Chips



11: Door osf
Dented
With Paint Damage

12: Door Mirror Assy osf
Scuffed (Unpainted)
Over 100mm



13: Wing osf
Scratched
Over 25mm Thru Paint

14: Bumper Front Moulding
Scuffed (Unpainted)
Over 100mm



15: Bumper Front
Dented
With Paint Damage

16: Bonnet
Dented
Over 30mm



17: Carpets Front
Missing
Replace

18: Switches And Controls
Missing
Replace

Interior

Carpet Condition	Average		Upholstery Condition	Average
Seat Condition	Average		Odour	-
Engine Runs	OK		Gearbox 1st and Reverse Test	OK
Brakes	OK		Clutch Slip Test from Static	OK
Turbo Boosting	OK		Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK		No Excessive Smoking	OK
EML light illuminated	OK		Oil warning light illuminated	OK
Airbag light illuminated	OK		DPF light illuminated	OK
ABS light illuminated	OK		Service indicator light illuminated	OK

Windows

OK

Radio

OK

Steering

OK