

VEHICLE INSPECTION REPORT

BN14WTT

Iveco Eurocargo 75E16

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date 19/03/2014

Year 2014

Mileage 382,904 Km Warranted

Fuel Type Diesel

Colour RED

VIN ZCFA675BX02623046

Body Style Box Van

Service history Yes

Service documents Printout

MOT Due 30/09/2026

Cab Type DAY CAB

Gearbox AUTOMATIC

Axle Combi 4x2

Rear Suspension Steel

WARNING LIGHT ON DASH

Tyres

NSF NSI1

OSF OSI1

Spare NSO1

OSO1

NSI2

OSI2

NSO2

OSO2

NSI3

OSI3

NSO3

OSO3

NSI4

OSI4

NSO4



OSO4

Features

- Cruise control
- Digital radio
- Radio/CD
- Front electric windows
- Central locking
- Cloth seat trim


Photos







Condition Check



Damage Photos



1: Door nsf
Scratched
Over 25mm Thru Paint

2: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



3: Qtr Panel osr
Scratched
Over 25mm Thru Paint



4: Door osf
Chipped
Multiple Chips



5: Seat Base Cover osf
Holed
Over 3mm



6: Dash Warning Lights
Displayed
No Action

7: Fascia Panel
Broken
Replace

Interior

Carpet Condition	OK	Upholstery Condition	Poor
Seat Condition	Poor	Odour	-
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	Fault	DPF light illuminated	OK
ABS light illuminated	OK		