

VEHICLE INSPECTION REPORT

PK67VFC

Daf CF 450

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date	06/11/2017	VIN	XLRTGM4100G180860	Cab Type	SLEEPER CAB
Year	2017	Body Style	Tractor Unit	Gearbox	AUTOMATIC
Mileage	954,353 Km Warranted	Service history	Yes	Axle Combi	6x2
Fuel Type	Diesel	Service documents	Printout	Steering Combi	Mid-Lift Steer
Colour	RED	MOT Due	Expired	Rear Suspension	Air

WARNING LIGHTS ON DASH, COLLECTED AS NON-RUNNER, BPV & SENSOR ISSUES


Tyres



NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features

- Cruise control
- Radio/CD
- Air conditioning
- Front electric windows
- Central locking
- Cloth seat trim


Photos







Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Panel Front
Scratched
Over 25mm Thru Paint



3: Door nsf
 Scratched
 Over 25mm Thru Paint

4: Door osf
 Scratched
 Over 25mm Not Thru Paint



5: Dash Warning Lights
 Displayed
 No Action

Interior

Carpet Condition	OK	Upholstery Condition	OK
Seat Condition	OK	Odour	-
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	Fault	DPF light illuminated	Fault
ABS light illuminated	OK		