

VEHICLE INSPECTION REPORT

YJ18FLP

Peugeot Boxer 335 2.0 BLUE HDI 130PS

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT
V5 Buyer To Apply

Details

Reg. date	09/04/2018	VIN	VF3YC2MFC12E70242	CAP Below	£3,550.00
Year	2018	Body Style	Crew Van L3	Gearbox	MANUAL
Mileage	78,593 Miles Not Warranted	MOT Due	08/05/2026	Gears	6
Fuel Type	Diesel	CAP Clean	£5,250.00		
Colour	WHITE	CAP Average	£4,525.00		

WARNING LIGHT ON DASH AD-BLUE, SIDE LOADING DOOR, E/MIRRORS

Tyres

NSF

NSR

OSF


OSR




Spare

Features

- Park assist camera
- Air conditioning
- Front electric windows


Photos







Condition Check



Damage Photos



1: Wing osf
Scratched
Over 25mm Thru Paint



2: Bonnet
Chipped
Multiple Chips



3: Other
N/A
N/A

4: Wing nsf
Chipped
Multiple Chips



5: Door Mirror Assy nsf
Scuffed (Unpainted)
Over 100mm

6: Flasher Side Repeater ns
Broken
Replace



7: Qtr Panel osr
Dented
Between 10mm + 30mm

8: Door osf
Scratched
UpTo 25mm Thru Paint



9: Flasher Side Repeater os
Broken
Replace

Interior

Carpet Condition	OK	Upholstery Condition	OK
Seat Condition	OK	Odour	No
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	Fault	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK