

VEHICLE INSPECTION REPORT

PE63NKF

Daf LF 45.140

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date 18/11/2013

Year 2013

Mileage 1,167,244 Km
Warranted

Fuel Type Diesel

Colour RED

VIN XLRAE45FF0L432725

Body Style Box Van

MOT Due 30/11/2026

Cab Type DAY CAB

Gearbox MANUAL

Axle Combi 4x2

Rear Suspension Steel

Tail Lift Cantilever

WARNING LIGHT ON DASH

Tyres

NSF NSI1 NSI2 NSI3 NSI4

OSF OSI1 OSI2 OSI3 OSI4

Spare NSO1 NSO2 NSO3 NSO4



OSO1 OSO2 OSO3 OSO4

Features


- Cruise control
- Radio/CD
- Front electric windows
- Central locking
- Cloth seat trim

Photos





Condition Check



Damage Photos




1: Bonnet
Chipped
Multiple Chips

2: Bumper Front
Dented
With Paint Damage



3: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



4: Qtr Panel osr
Scratched
Over 25mm Thru Paint



5: Door osf
Dented
With Paint Damage




6: Door osf
Scratched
Over 25mm Thru Paint



7: Screen Front
Chipped
Over 10mm



8: Seat Base Cover nsf
Torn
Over 3mm





9: Dash Warning Lights
 Displayed
 No Action

Interior

Carpet Condition	OK	Upholstery Condition	OK
Seat Condition	Poor	Odour	-
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	Fault
ABS light illuminated	OK		