

VEHICLE INSPECTION REPORT

PF14T2M

Daf LF 150

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date 21/08/2014

VIN XLRAEL1500L438085

Gearbox MANUAL

Year 2014

Body Style Box Van

Axle Combi 4x2

Mileage 892,634 Km Warranted

Service history Yes

Rear Suspension Steel

Fuel Type Diesel

MOT Due 30/04/2026

Tail Lift Cantilever

Colour RED

Cab Type DAY CAB

Tyres

NSF NSI1 NSI2 NSI3 NSI4

OSF OSI1 OSI2 OSI3 OSI4

Spare NSO1 NSO2 NSO3 NSO4




OSO1 OSO2 OSO3 OSO4


Features

- Cruise control
- Radio/CD
- Front electric windows
- Central locking
- Cloth seat trim


Photos







Condition Check



Damage Photos



1: Bumper Front
Dented
With Paint Damage

2: Door nsf
Scratched
Over 25mm Not Thru Paint



3: Door osf
Dented
With Paint Damage

4: Door osf
Scratched
Over 25mm Thru Paint



5: Seat Base Cover nsf
Holed
Over 3mm

6: Door Pad osf
Soiled
Heavy



7: Bumper Front
Scratched
Over 100mm Thru Paint

8: Bonnet
Chipped
Multiple Chips

Interior

Carpet Condition	OK	Upholstery Condition	Poor
Seat Condition	Poor	Odour	-
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		