

VEHICLE INSPECTION REPORT

PJ16YUH

DAF CF 440

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date 26/08/2016

Year 2016

Mileage 1,281,305 Km
Warranted

Fuel Type Diesel

Colour RED

VIN XLRTGM4100G122153

Body Style Tractor Unit

Service history Yes

Service documents Printout

MOT Due 31/07/2025

Cab Type SLEEPER CAB

Gearbox AUTOMATIC

Axle Combi 6x2

Steering Combi Mid-Lif Steert

Rear Suspension Air

WARNING LIGHT ON DASH MOT HISTORY IN MILES & KMS

Tyres

NSF NSI1

OSF OSI1

Spare NSO1

NSI2

OSI2

NSO2

OSO1

NSI3

OSI3

NSO3

OSO2

NSI4

OSI4

NSO4


OSO3

Features

- Bluetooth connection
- Air conditioning
- Cloth seat trim
- Cruise control
- Front electric windows
- Radio/CD
- Drivers airbag
- Manual sunroof
- Central locking


Photos







Condition Check



Damage Photos



1: Panel Front
Cracked
Replace



2: Bumper Front
Dented
With Paint Damage



3: Moulding osf Wing
Scuffed (Unpainted)
Over 100mm



4: Panel Front
Scratched
Over 25mm Thru Paint



5: Qtr Panel osr
Missing
Replace



6: Bumper Front
Scratched
Over 100mm Thru Paint



7: Carpets Front
Missing
Replace



8: Seat Base Cover osf
Holed
Over 3mm

Interior

Carpet Condition	Poor	Upholstery Condition	Average
Seat Condition	Average	Odour	-
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK