

VEHICLE INSPECTION REPORT

093016

LIUGONG 922E

Inspection

Vehicle

VAT	Plus VAT
V5	N/A

Details

Reg. date	01/01/2021	Fuel Type	DIESEL	Body Style	Excavator
Year	2021	Colour		Gearbox	HYDROSTATIC
Mileage	3,695 Hours Not Warranted	VIN	CLG922EZEME0930016		

3 X BUCKETS, QUICK HITCH, HAMMER PIPEWORK, REVERSING CAMERA, CAMERA ON ARM

Tyres

NSF

NSR

OSF

OSR

Spare

Photos





