

VEHICLE INSPECTION REPORT

PE63MYV

Daf LF 45.140

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date 18/10/2013

Year 2013

Mileage 564,696 Km Warranted

Fuel Type Diesel

Colour RED

VIN XLRAE45FF0L431616

Body Style Box Van

MOT Due 30/06/2026

Cab Type DAY CAB

Gearbox MANUAL

Rear Suspension Steel

Tail Lift Cantilever

COLLECTED AS NON-RUNNER

Tyres

NSF NSI1 NSI2 NSI3 NSI4

OSF OSI1 OSI2 OSI3 OSI4

Spare NSO1 NSO2 NSO3 NSO4


OSO1 OSO2 OSO3 OSO4

Features


- Cruise control
- Cloth seat trim
- Radio/CD
- Front electric windows
- Central locking

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips

2: Bumper Front Moulding
Scuffed (Unpainted)
Over 100mm



3: Door Moulding nsf
Broken
Replace

4: Door osf
Chipped
Multiple Chips



5: Screen Front
Chipped
Over 10mm

Interior

Carpet Condition	OK	Upholstery Condition	OK
Seat Condition	OK	Odour	-
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		