

VEHICLE INSPECTION REPORT

PN14WYD

Daf LF 150

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date 03/04/2014

VIN XLRAEL1500L435433

Gearbox MANUAL

Year 2014

Body Style Box Van

Axle Combi 4x2

Mileage 916,696 Km Warranted

Service history Yes

Rear Suspension Steel

Fuel Type Diesel

MOT Due 31/03/2026

Tail Lift Cantilever

Colour RED

Cab Type DAY CAB

Tyres

NSF NSI1 NSI2 NSI3 NSI4

OSF OSI1 OSI2 OSI3 OSI4

Spare NSO1 NSO2 NSO3 NSO4


OSO1 OSO2 OSO3 OSO4

Features

- Cruise control
- Cloth seat trim
- Radio/CD
- Front electric windows
- Central locking


Photos







Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front
Scratched
Over 100mm Thru Paint



3: Door osf
 Scratched
 Over 25mm Thru Paint

4: Fascia Trim
 Damaged
 Replace

Interior

Carpet Condition	OK	Upholstery Condition	Poor
Seat Condition	OK	Odour	-
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		