

# VEHICLE INSPECTION REPORT

**SJ16NVL**

## Mercedes-Benz Econic

Non Runner

### Inspection

Serious Damage? No

### Vehicle

VAT Plus VAT

V5 Buyer To Apply

### Details

Reg. date 29/03/2016

Colour GREY

Gearbox AUTOMATIC

Year 2016

VIN WDB9560332V242214

Axle Combi 6x2

Mileage Not Showing

Body Style Chassis Cab

Fuel Type Electric

Cab Type CREW CAB

\*CRANE REQUIRED FOR COLLECTION\* \*NON-RUNNER - STRIPPED, DOES NOT POWER UP\* C/W FAUN VARIPRESS 521V19 BODY (YEAR 2016), MOT SHOWS 57,333KM 13/03/2024

### Tyres

NSF NSI1

NSI2

NSI3

NSI4

OSF OSI1

OSI2

OSI3

OSI4

Spare NSO1

NSO2

NSO3

NSO4

OSO1




OSO2


OSO3

OSO4


### Photos







## Condition Check



## Damage Photos



1: Number Plate Front  
Broken  
Replace

2: Fog Lamp Surrounds  
Broken  
Replace



3: Other  
N/A  
N/A

**Interior**

|                         |    |                             |    |
|-------------------------|----|-----------------------------|----|
| <b>Carpet Condition</b> | OK | <b>Upholstery Condition</b> | OK |
| <b>Seat Condition</b>   | OK | <b>Odour</b>                | -  |
| <b>Engine Runs</b>      |    | <b>Fault</b>                |    |