

VEHICLE INSPECTION REPORT

BN14WSX

Iveco Eurocargo 75e16

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 To Follow

Details

Reg. date	19/03/2014	VIN	ZCFA675B102623064	Cab Type	DAY CAB
Year	2014	Body Style	Box Van	Gearbox	MANUAL
Mileage	395,383 Km Warranted	Service history	Yes	Axle Combi	4x2
Fuel Type	Diesel	Service documents	Printout	Rear Suspension	Steel
Colour	RED	MOT Due	30/04/2026	Tail Lift	Cantilever

COLLECTED AS NO-RUNNER, WARNING LIGHT ON DASH

Tyres

NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4


Features

- Cruise control
- Radio/CD
- Front electric windows
- Central locking
- Cloth seat trim

Photos



Condition Check



Damage Photos



1: Bonnet
Scratched
Over 25mm Thru Paint

2: Door nsf
Chipped
Multiple Chips



3: Qtr Panel nsr
Scratched
Over 25mm Thru Paint

4: Qtr Panel osr
Scratched
Over 25mm Thru Paint



5: Qtr Panel osr
Scratched
Over 25mm Thru Paint

6: Door osf
Scratched
Over 25mm Thru Paint



7: Dash Warning Lights
Displayed
No Action

Interior

Carpet Condition	OK	Upholstery Condition	OK
Seat Condition	OK	Odour	-
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	Fault
ABS light illuminated	OK		