

VEHICLE INSPECTION REPORT

WU74VSO

Iveco Daily 35-140

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Buyer To Apply

Details

Reg. date 06/12/2024

Year 2024

Mileage 44,686 Km Not Warranted

Fuel Type Diesel

Colour WHITE

VIN ZCFCL35A305629626

Body Style Crew Van MWB

MOT Due 05/12/2027

Gearbox AUTOMATIC

Gears 8

NEAR SWINDON *WARNING LIGHT ON DASH* TWIN SIDE LOADING DOORS, E/MIRRORS, AD BLUE, TOW BAR

Tyres

NSF

NSR

OSF


OSR



Spare

Features


- Navigation system
- Park assist camera
- Air conditioning
- Front electric windows

Photos





Condition Check



Damage Photos



1: Door osr
Chipped
Over 5mm

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	No

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	Fault	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK