

VEHICLE INSPECTION REPORT

DK17KXC

Man TGS 26.360

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 To Follow

Details

Reg. date	26/04/2017	Colour	BLUE	Cab Type	DAY CAB
Year	2017	VIN	WMA18SZZ7HM730876	Gearbox	MANUAL
Mileage	205,545 Km Warranted	Body Style	Dropside & Crane	Axle Combi	6x2
Fuel Type	Diesel	MOT Due	30/04/2026	Rear Suspension	Air

REAR LIFT AXLES, HMF 1420K2 (2 EXT) REMOTE CRANE (YEAR 2017) , SERVICE SCHEDULE LIST AVAILABLE

Tyres


NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features

- Bluetooth connection
- Cruise control
- Park assist camera
- Digital radio
- Front electric windows
- Central locking
- Cloth seat trim


Photos







Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips

2: Bumper Front Moulding
Scuffed (Unpainted)
Over 100mm



3: Wing nsf
Scratched
Over 25mm Thru Paint

4: Bumper Rear
Dented
With Paint Damage



5: Wing osf
Scratched
Over 25mm Thru Paint

6: Door osf
Scratched
Over 25mm Thru Paint



7: Door osf
Dented
Over 30mm

8: Seat Base Cover osf
Holed
Over 3mm

Interior

Carpet Condition	OK	Upholstery Condition	OK
Seat Condition	Poor	Odour	-
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		