

VEHICLE INSPECTION REPORT

PJ71VAA

Scania R 450

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date 10/12/2021

Year 2021

Mileage 427,023 Km Not Warranted

Fuel Type Diesel

Colour WHITE

VIN YS2R6X20005645037

Body Style Tractor Unit

MOT Due 31/10/2027

Cab Type HIGHLINE CAB

Gearbox AUTOMATIC

Axle Combi 6x2

Steering Combi Mid-Lift

Rear Suspension Air

WARNING LIGHT ON DASH SLIDING 5TH WHEEL, REAR VIEW CAMERA, PREMIUM INFOTAINMENT SYSTEM, PREMIUM DASH

Tyres

NSF NSI1 NSI2 NSI3 NSI4

OSF OSI1 OSI2 OSI3 OSI4


Spare NSO1 NSO2 NSO3 NSO4





OSO1 OSO2 OSO3 OSO4

Features


- Radio/CD
- Air conditioning
- Leather seat trim

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
1 To 5

2: Wing osf
Chipped
1 To 5

Interior

Carpet Condition OK
Seat Condition OK

Upholstery Condition OK
Odour -

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	Fault	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK