

VEHICLE INSPECTION REPORT

YP67ZZU

FORD TRANSIT COURIER 1.5 TDCI 95PS

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 To Follow

Details

Reg. date 20/11/2017

Year 2017

Mileage 90,340 Miles
Warranted

Fuel Type Diesel

Colour WHITE

VIN WF0WXXTACWHC42548

Body Style Panel Van SWB

CAP Clean £3,550.00

CAP Average £3,000.00

CAP Below £2,300.00

Gearbox MANUAL

Gears 5

WARNING LIGHT ON DASH *OUTSTANDING RECALL* SIDE LOADING DOOR, E/MIRRORS

Tyres

NSF

NSR

OSF



OSR

Spare

Features


- Front electric windows

Photos





Condition Check



Damage Photos



1: Door Mirror Assy osf
Scratched (Painted)
UpTo 25mm Thru Paint

2: Screen Front
Chipped
UpTo 10mm



3: Bonnet
Chipped
Multiple Chips

4: Door Mirror Assy nsf
Scratched (Painted)
UpTo 25mm Not Thru Paint



5: Bumper Rear
Scratched
Over 25mm Not Thru Paint

6: Bumper Rear Moulding
Scuffed (Unpainted)
UpTo 100mm



7: Bumper Rear Moulding
Scuffed (Unpainted)
UpTo 100mm

8: Qtr Panel osr
Scratched
Rusted



9: Sill Panel Trim os
Scuffed (Unpainted)
Over 100mm

10: Sill Panel Trim ns
Scuffed (Unpainted)
Over 100mm



11: Bumper Front
Chipped
1 To 5

Interior

Carpet Condition	Average		Upholstery Condition	Average
Seat Condition	Average		Odour	No
Engine Runs	OK		Gearbox 1st and Reverse Test	OK
Brakes	OK		Clutch Slip Test from Static	OK
Parking Brake	OK		Gearbox Static Gear Selection (engine running)	OK
			No Excessive Smoking	OK
EML light illuminated	OK		Oil warning light illuminated	OK
Airbag light illuminated	OK		DPF light illuminated	OK
ABS light illuminated	OK		Service indicator light illuminated	Fault