

# VEHICLE INSPECTION REPORT

**WR20DXD**

## Fiat Ducato 35 MAXI 2.3 MULTIJET 140PS

### Inspection

Serious Damage? No

### Vehicle

VAT Plus VAT

V5 Present

### Details

Reg. date 29/06/2020

VIN ZFA25000002N79865

CAP Below £5,600.00

Year 2020

Body Style Panel Van MWB

Gearbox MANUAL

Mileage 77,792 Miles  
Warranted

MOT Due 28/06/2025

Gears 6

CAP Clean £7,650.00

Axle Combi 4x2

Fuel Type Diesel

CAP Average £6,825.00

Colour WHITE

A/C, AD-BLUE, SAT NAV, SINGLE SIDE DOOR, FRONT & REAR SENSORS, E/WINDOWS & MIRRORS, REAR CAMERA

\*TURBO ISSUES\*

### Tyres

NSF

NSR

OSF

OSR

Spare


### Photos







## Condition Check



## Damage Photos



1: Screen Front  
Chipped  
UpTo 10mm



2: Door Mirror Assy nsf  
Broken  
Replace



3: Door Mirror Assy nsf  
Broken  
Replace



4: Qtr Panel osr  
Dented  
Over 30mm



5: Door osf  
Scratched  
Over 25mm Not Thru Paint



6: Carpets Front  
Holed  
Over 3mm



7: Seat Base Cover osf  
Holed  
Over 3mm

## Interior

<b>Carpet Condition</b>	<b>Average</b>	<b>Upholstery Condition</b>	<b>Average</b>
<b>Seat Condition</b>	<b>Average</b>	<b>Odour</b>	<b>No</b>
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK