

# VEHICLE INSPECTION REPORT

**NA66DTY**

## Mercedes-Benz Sprinter 316 CDI

### Inspection

Serious Damage? No

### Vehicle

VAT Plus VAT

V5 To Follow

### Details

Reg. date 01/12/2016

Year 2016

Mileage 184,102 Miles  
Warranted

Fuel Type Diesel

Colour WHITE

VIN WDB9066352P344294

Body Style Panel Van LWB

MOT Due 30/11/2025

CAP Clean £3,625.00

CAP Average £3,000.00

CAP Below £2,300.00

Gearbox MANUAL

### SIDE LOAD DOOR

### Tyres

NSF

NSR

OSF

OSR

Spare

## Features

- Bluetooth connection
- Drivers airbag
- Cruise control
- Passenger airbag
- Radio/CD
- Central locking
- Front electric windows
- Cloth seat trim

## Photos












## Condition Check



## Damage Photos



1: Roof  
Chipped  
Multiple Chips



2: Bonnet  
Chipped  
Multiple Chips



3: Qtr Panel nsr  
Dented  
Over 30mm



4: Qtr Panel nsr  
Rusted  
Over 5mm



5: Qtr Panel osr  
Rusted  
Over 5mm



6: Qtr Panel Moulding os  
Scuffed (Unpainted)  
Over 100mm

## Interior

**Carpet Condition** OK  
**Seat Condition** OK

**Upholstery Condition** OK  
**Odour** Yes

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK