



COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE

01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

5016187

Iveco Daily 65-170

Inspection		Vehicle	
Serious Damage?	No	VAT	Plus VAT
		V5	Buyer To Apply

Details

Reg. date	15/06/2015	VIN	ZCFC265C905016187	Axle Combi	4x2
Year	2015	Body Style	Box Van	Rear Suspension	Steel
Mileage	105,552 Km Warranted	MOT Due	31/10/2026	Rear Doors	Barn
Fuel Type	DIESEL	Cab Type	DAY CAB	Tail Lift	Cantilever
Colour		Gearbox	MANUAL		

TAIL LIFT & STABILIZER LEGS IN-OP MOD 654 FORM IN OFFICE, AD-BLUE

Tyres


NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features


- Air conditioning

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips

2: Screen Front
Chipped
UpTo 10mm



3: Wing osf
Chipped
1 To 5



4: Bumper Front Moulding
Scuffed (Unpainted)
Over 100mm



5: Bumper Front Moulding
Scratched (Painted)
Up To 25mm Not Thru Paint



6: Bumper Front Moulding
Scuffed (Unpainted)
Over 100mm



7: Wing nsf
Chipped
1 To 5



8: Wing Front Arch Extension ns
Scuffed (Unpainted)
Over 100mm



9: Door Mirror Assy nsf
Scuffed (Unpainted)
Over 100mm

10: Door Moulding nsf
Scuffed (Unpainted)
Over 100mm



11: Door nsf
Scratched
Over 25mm Thru Paint

12: Door nsf
Chipped
Edge Chip



13: Door nsr
Scratched
Over 25mm Thru Paint

14: Qtr Panel Moulding ns
Scuffed (Unpainted)
Over 100mm



15: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint



16: Panel Rear
Scratched
Over 25mm Not Thru Paint



17: Qtr Panel Moulding os
Scuffed (Unpainted)
Over 100mm



18: Door osf
Chipped
1 To 5



19: Door Mirror Assy osf
Scuffed (Unpainted)
Over 100mm



20: Seat Base Cover osf
Torn
Over 3mm

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	-
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK