

# VEHICLE INSPECTION REPORT

**YR69DOU**

## Ford Ranger Pick Up Double Cab XL 2.0 TDCI EcoBlue 170 PS

### Inspection

Serious Damage? No

### Vehicle

VAT Plus VAT

V5 Buyer To Apply

### Details

Reg. date 02/09/2019

Year 2019

Mileage 107,807 Miles Not Warranted

Fuel Type Diesel

Colour WHITE

VIN 6FPPXXMJ2PKL12882

Body Style Pickup Double Cab

MOT Due 01/09/2025

CAP Clean £8,600.00

CAP Average £7,525.00

CAP Below £6,025.00

Gearbox MANUAL

Gears 6

Doors 4

Axle Combi 4x4

Rear Suspension Steel

\*WARNING LIGHTS ON DASH\*

### Tyres

NSF

NSR

OSF


OSR




Spare

## Features

- Bluetooth connection
- Front electric windows
- Central locking
- Park assist camera
- Rear electric windows
- Cloth seat trim
- USB/iPod interface
- Drivers airbag
- Air conditioning
- Passenger airbag


## Photos







## Condition Check



## Damage Photos



1: Seat Base Cover osf  
Torn  
Over 3mm



2: Sill os  
Rusted  
Over 5mm



3: Bonnet  
Chipped  
Multiple Chips



4: Wing osf  
Chipped  
1 To 5



5: Door osf  
Dented  
2 Or Less UpTo 10mm



6: Qtr Panel nsr  
Dented  
Between 10mm + 30mm



7: Door nsr  
Dented  
2 Or Less UpTo 10mm



8: Door nsf  
Chipped  
1 To 5

## Interior

Carpet Condition		Upholstery Condition	
Seat Condition	Average Poor	Odour	Average No
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	Fault	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
		Steering	OK