

VEHICLE INSPECTION REPORT

DK67VVB

MAN TGM 18.250

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 To Follow

Details

Reg. date	15/09/2017	Colour	BLUE	Cab Type	DAY CAB
Year	2017	VIN	WMAN08ZZ5HY363612	Gearbox	MANUAL
Mileage	226,195 Km Warranted	Body Style	Dropside & Crane	Axle Combi	4x2
Fuel Type	Diesel	MOT Due	31/07/2026	Rear Suspension	Steel

HMF 1420 CRANE (YEAR 2017), SERVICE SCHEDULE LIST & LAST CRANE TEST AVAILABLE


Tyres




NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4


Features

- Bluetooth connection
- Cruise control
- Park assist camera
- Digital radio
- Front electric windows
- Central locking
- Cloth seat trim


Photos







Condition Check




Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Wing nsf
Chipped
Multiple Chips



3: Wing osf
Chipped
Multiple Chips

4: Door osf
Scratched
Over 25mm Thru Paint



5: Seat Base Cover osf
Holed
Over 3mm

Interior

Carpet Condition		OK	Upholstery Condition		OK
Seat Condition		Poor	Odour		-
Engine Runs	OK		No Excessive Smoking		OK
EML light illuminated	OK		DPF light illuminated		OK
ABS light illuminated	OK				