

VEHICLE INSPECTION REPORT

KU69YGW

VOLVO FH 500

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT
V5 Buyer To Apply

Details

Reg. date	01/10/2019	Colour	BLUE	Gearbox	AUTOMATIC
Year	2019	VIN	YV2RTY0C3KB921116	Axle Combi	6x2
Mileage	719,848 Km Not Warranted	Body Style	Tractor Unit	Steering Combi	Mid-Lift
Fuel Type	Diesel	Cab Type	GLOBETROTTER CAB	Rear Suspension	Air

WARNING LIGHTS ON DASH SLIDING 5TH WHEEL

Tyres





NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features

- Bluetooth connection
- Air conditioning
- Cloth seat trim
- Cruise control
- Front electric windows
- Auxiliary input socket
- Drivers airbag
- Digital radio
- Central locking


Photos







Condition Check



Damage Photos



1: Panel Front
Scratched
Over 25mm Not Thru Paint



2: Door nsf
Dented
Over 30% Of Panel



3: Qtr Panel Trim ns
Broken
Replace

4: Dash Warning Lights
Displayed
No Action

Interior

Carpet Condition		OK	Upholstery Condition		OK
Seat Condition		OK	Odour		-
Engine Runs		OK	No Excessive Smoking		OK
EML light illuminated		OK			
ABS light illuminated		Fault			