

VEHICLE INSPECTION REPORT

LX20NVT

Porsche Cayenne V6 E-HYBRID

Inspection

Serious Damage? No

Vehicle

VAT VAT Qualifying

V5 Buyer To Apply

nama
GRADE
2

Details

Reg. date	06/03/2020	VIN	WP1ZZZ9YZLDA74163	CAP Below	£34,400.00
Year	2020	Body Style	SUV	Gearbox	AUTOMATIC
Mileage	57,515 Miles Not Warranted	MOT Due	16/04/2026	Gears	8
Fuel Type	Hybrid Electric	CAP Clean	£37,100.00	Axle Combi	4x4
Colour	BLACK	CAP Average	£35,700.00		

KEYLESS IGNITION

Tyres

NSF

NSR

OSF

OSR





Spare

Features

- Bluetooth connection
- Navigation system
- Steering wheel mounted controls
- Air conditioning
- Drivers airbag
- Alarm
- Cruise control
- Park assist camera
- Trip computer
- Climate control
- Passenger airbag
- Remote central locking
- Front parking sensor
- Rear parking sensor
- Body coloured bumpers
- Electrically adjustable drivers seat
- Rear airbags
- Leather seat trim
- Heated front seat
- Reverse parking aid
- Electric door mirrors
- Front electric windows
- Side airbags
- Alloy wheels


Photos







Condition Check



Damage Photos



1: Bumper Front
Chipped
1 To 5

2: Sill Panel Trim os
Scuffed (Unpainted)
Over 100mm



3: Sill Panel Trim ns
Scuffed (Unpainted)
Over 100mm

4: Wheel osr
Scratched
Over 50mm



5: Wheel osf
Scratched
Over 50mm

6: Wheel nsf
Scratched
Over 50mm



7: Wheel nsr
Scratched
Over 50mm

Interior

Carpet Condition	OK	Upholstery Condition	OK
Seat Condition	OK	Odour	No
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK