

VEHICLE INSPECTION REPORT

RE21JUH

IVECO DAILY 70-210 ILES BUS

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Buyer To Apply

Details

Reg. date 03/06/2021

Year 2021

Mileage 184,050 Km Not Warranted

Fuel Type Diesel

Colour WHITE

VIN ZCFC670F705327418

Body Style Coach

Keys 1

MOT Due 04/06/2026

Gearbox AUTOMATIC

Axle Combi 4x2

WARNING LIGHTS ON DASH 29 SEATER + DRIVER + CREW SEAT, CONTINENTAL SIDE DOOR, OVERHEAD STOWAGE, 3 PT. SEATBELTS


Tyres

NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features


- Bluetooth connection
- Air conditioning
- Leather seat trim

Photos





Condition Check




Damage Photos



1: Wing osf
Chipped
Over 5mm



2: Door nsf
Chipped
Multiple Chips



3: D Post ns
Dented
With Paint Damage

4: Bumper Rear
Cracked
Over 25mm



5: Qtr Panel osr
Rusted
Over 5mm

Interior

Carpet Condition	OK	Upholstery Condition	OK
Seat Condition	OK	Odour	-
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	Fault	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	Fault	No Excessive Smoking	OK
Airbag light illuminated	OK	Oil warning light illuminated	Fault
ABS light illuminated	Fault	DPF light illuminated	Fault
		Service indicator light illuminated	OK

Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK